


F024 - REMOVAL AND RECOVERY OF COPPER-OVERHEAD COMPONENTS AND CABLING



openreach



Introduction

This course provides learners with the knowledge & skills to safely & competently undertake F024 - Removal & Recovery of Copper Overhead Components & Cabling.

Certification

Upon successful completion, learners will receive a certificate of accreditation for Openreach F024 - Removal & Recovery of Copper Overhead Components & Cabling.

Accreditation

Openreach accreditation certificate by Smart Awards.

Delivery

To deliver Openreach accreditations, training providers must have a Lead Assessor or Assessor who is formally approved and certificated by Openreach. The approved Lead Assessor or Assessor must be registered on the Network Operative Passport Scheme (NOPS), with their relevant Openreach certification uploaded, before they can assess or deliver the accreditation.

Where an accreditation includes a practical assessment, the training site must be approved and signed off by Openreach before delivery can take place. Training providers must contact Smart Awards to complete the registration process and gain approval to deliver Openreach accreditations.